

IES file 90° declined ==> light distribution not what it supposed to be (no light on the floor + asymetric on the wall